

Walk-in Booths

Walk in Booths (also called Cabin Booths) are ideal when coating large and bulky or heavy parts.

As the name suggests, after the part to be coated has been rolled into the cabin, the operator walks in and coats the parts from all sides.

These parts are then rolled out directly into the powder curing oven.

These booths find use in batch system for control panels, cabinet, large iron cast products, etc.

Walk in Booths also could have mono Cyclones as a recovery system.



COLO-S-3222



Model	COLO-S-3222
Working dimensions	W3000 *H2000 *D1700mm
Overall dimensions	W3080 *H2080*D2200mm
Filters count	4 pcs.
Nominal power	4kw
Nominal voltage	As required
Air consumption	4000m3/h